National Transportation Safety Board NTSB ID: DCA05RA094 Aircraft Registration Number: TS-LBB FACTUAL REPORT Occurrence Date: 08/06/2005 Most Critical Injury: Fatal Occurrence Type: Accident Investigated By: ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone 1338 UTC Palermo Distance From Landing Facility: Direction From Airport: Airport Proximity: Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft ATR ATR-72-202 Airplane

Narrative

Sightseeing Flight: No

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On August 6, 2005, a Tunisian registered ATR-72 suffered a dual engine flameout and ditched in the ocean 11 NM northeast of Capo Gallo, Palermo, Sicily, Italy. There were 4 crew members and 29 passengers on board. One cabin crew member and 15 passengers suffered fatal injuries, the remaining occupants sustained minor to serious injuries.

Air Medical Transport Flight: No

The flight departed Bari, Italy at 12.32 UTC. Approximately 45 minutes later, while cruising at FL 230, the number 2 (right) engine failed and the crew elected to divert to Palermo Punta Raisi airport with only one engine operating. About 3 to 4 minutes later, at 17,000 feet, the number 1 (left) also failed. The crew reported that they attempted to restart the engines with no success. After gliding for about 16 minutes, the crew was forced to perform and emergency water ditching approximately 23 NM offshore from Palermo airport. The aircraft broke into three parts after impacting the sea surface.

The Italian ANSV is investigating, and the NTSB is assisting with extracting data from the Electronic Engine Controls manufactured by Hamilton Sundstrand Corp.

The ANSV has issued safety recommendations regarding the fuel quantity measuring and warning system.

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: DCA05RA094

Occurrence Date: 08/06/2005

AVIATION			Occurrence Type: Accident									
Landing Facility/Approach Info	rmation											
Airport Name Airp			Airport ID:		Airport Elevation Runw Ft. MSL			way Used Runway Length			Runw	vay Width
Runway Surface Type:												
Runway Surface Condition:												
Type Instrument Approach:												
VFR Approach/Landing:												
Aircraft Information			_									
Aircraft Manufacturer ATR			Model/ ATR-	Series 72-202					Serial	al Number		
Airworthiness Certificate(s):												
Landing Gear Type:												
omebuilt Aircraft? No Number of Seats:				d Max Gross W	LBS Numbe			er of En	gines:	:		
Engine Type: En				Engine Manufacturer: Model/Series:						Rated Power:		
- Aircraft Inspection Information												
Type of Last Inspection Date			Date of Last Inspection Time Sinc				nce Last Inspection Hours			Airframe Total Time Hours		
- Emergency Locator Transmitter (EL	T) Information											
ELT Installed?			ELT	Aided i	n Locating Ad	cident S	ite?					
Owner/Operator Information												
Registered Aircraft Owner			Street Address									
			City								е	Zip Code
Operator of Aircraft Street Address												
Tuninter			City							Stat	е	Zip Code
Operator Does Business As: Operator Designator Code:												
- Type of U.S. Certificate(s) Held: No	ne											
Air Carrier Operating Certificate(s):												
Operating Certificate: Operator Certificate:												
Regulation Flight Conducted Under: Non-U.S., Commercial												
Type of Flight Operation Conducted: Scheduled; International; Passenger Only												
	I	FACTU	AL REPO	RT - AVIAT	ION							Page 2

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DCA05RA094

Occurrence Date: 08/06/2005

AVIATION				Occurrence Type: Accident											
First Pilot Information															
Name City State Date of Birth										Age					
On File	n File														
Sex: Seat Occupied: Principal Profession: Certificate Number:															
Certificate(s):															
Airplane Rating(s):															
Rotorcraft/Glider/LTA:															
Instrument Rating(s	s):														
Instructor Rating(s):															
Type Rating/Endors	sement fo	or Accident/Ir	ncident Aircra	ft?			С	urrent B	siennia	l Flight R	eview	/ ?			
Medical Cert.:		Medica	al Cert. Statu	s:					D	ate of La	ast Me	edical E	I Exam:		
		•													
- Flight Time Matrix	(All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Actual	Instrument tual Simulated			Rotorcraft	Glider	Lighter Than Air	
Total Time															
Pilot In Command(PI	C)					-					4				
Instructor						+	\dashv				+				
Last 90 Days Last 30 Days						-	\dashv		-+		+				
Last 24 Hours						1	\dashv				+				
Seatbelt Used?		Shou	ılder Harness	: Used?	1		oxico	ology Pe	rforme	ed?		Se	econd Pilot?		
- Coalson Coou.		01100	naci i lairiese												
Flight Plan/Itine	rarv														
Type of Flight Plan		 R													
Departure Point							State Airport			rport Identifier Dep		Depar	rture Time	Time Zone	
Bari									LIBD						
Destination State Airport Identifier															
Jerba							DT			DTTS					
Type of Clearance:															
Type of Airspace:															
Weather Informa	ation														
Source of Briefing:															
Method of Briefing:		<u> </u>													
				FACTUAI	L REPORT	- AVIA	ΓΙΟΝ	N						Page 3	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DCA05RA094

Occurrence Date: 08/06/2005

Occurrence Type: Accident

	ETYBOR		00	currenc	ce Type:	Accide	nt							
Weather Information														
WOF ID	Observation Time	Time Zone	WOF	Elevati	ion	WOF Distance From Accident Site				Direction From Accident Site				
				E+	. MSL		NIA				Dog Mos			
					IVISL	<u> </u>			NM	Deg. Mag.				
Sky/Lowest Cloud Condition:							Ft. AGL	L	Condition o	ndition of Light:				
Lowest Ce	Lowest Ceiling: Ft					Visil	oility:		SM	Altii	Altimeter:			
Temperatu	ure: °C	Dew Point:		°C	Wind	Vind Direction: Density Altitude:						Ft.		
Wind Spee	Wind Speed: Gusts: Weather Condtions at Accident Site: Visual Conditions													
Visibility (F	RVR): Ft.	Visibility	y (RVV)		SM	Intensi	ty of Precipitat	tion:						
Restriction	ns to Visibility:													
Type of Pro	ecipitation:													
Accident	Information													
Aircraft Damage: Destroyed Aircraft Fi					e:				Aircraft Exp	losio	n			
Classificati	ion:													
- Injury Su	mmary Matrix	Fatal	Serious	Mino	or	None	TOTAL							
First Pi	ilot		1				1							
Second	d Pilot		1				1							
Studen	nt Pilot													
Flight I	nstructor													
Check	Pilot													
Flight E	Engineer													
Cabin /	Attendants	1	1				2							
Other C	Crew													
Passer	ngers	15	20				35							
- TOTAL /	ABOARD -	16	23				39							
Other 0	Ground													
- GRANE	O TOTAL -	16	23				39							

National Transportation Safety Bo	ard
FACTUAL REPORT	

NTSB ID: DCA05RA094

FACTUAL REPORT	Occurrence Date: 08/06/2005	
AVIATION	Occurrence Type: Accident	
Administrative Information		
Investigator-In-Charge (IIC)		
William English		
Additional Persons Participating in This Accident/Incide	ent Investigation:	